Request for Well and Septic Service

WLS-006

- 🍫

PURPOSE: This form is used to request a paid service from the Well & Septic Division of the Permit and Resource Management Department (PRMD) related to an existing or proposed septic system. A permit application may be required following the requested service.

*

No 🗖	Cross Street Assessor's Parcel Number Property Owner's Name Mailing Address Day Phone LINE - To Be Completed by PRMD Staff Violation # nents/Notations	
State/Zip	Property Owner's Name Mailing Address Day Phone LINE - To Be Completed by PRMD Staff Violation #	U
TE BELOW THIS I	Mailing Address Day Phone LINE - To Be Completed by PRMD Staff Violation #	U
TE BELOW THIS I	Day Phone LINE - To Be Completed by PRMD Staff Violation #	U
No 🗖	LINE - To Be Completed by PRMD Staff Violation #	
No 🗖	Violation #	
No 🗖	Violation #	
Staff Comn	nents/Notations	
Staff Comn	nents/Notations	
	Date Completed	
	osa, CA 🛠 95	Date Completed Ermit and Resource Management Deg Osa, CA \$ 95403-2829 \$ (707) 565-1900 \$ Divide Request for Well and Septic Service.wpd 03/09/06



"A Service You Can Count On!"

November 2, 2023

Site Address:4200 Canfield RoadAPN:025-110-006Job Number:23269

The purpose of this report is to present the findings and conditions of the existing onsite sewage disposal system currently serving the farmworker house at 4200 Canfield Road. There is also a main house on the parcel. This report does not cover the existing septic system serving the main house. The site is located on the west side of Canfield Road, approximately 3,200' south of its intersection with Blank Road.

Sonoma County records were searched, and nothing was found on file.

On October 13, 2023, we visited the site. It was determined that the system consisted of a 1,200 gallon fiberglass septic tank, followed by a 500 gallon fiberglass sump tank that pumps to three 130' leach lines with a depth of 40". The septic tank was not pumped at this time, but per the owner and based upon the volume of solids in the tank it had been pumped recently. The effluent level in the tank was normal. The septic tank contained inlet and outlet sanitary tees. A load test of approximately 150 gallons was applied to the leach field from the sump tank. There was no backup and the pump had no issues. The hydraulic load test received a rating of good. The leach field appeared to be functioning adequately, no surfacing or breakout was observed. No reserve area is identified on any documents retrieved from Permit Sonoma, but replacement of the leach field appears feasible.

It is our opinion that this 2-bedroom septic system meets legal non-conforming standards with respect to current Sonoma County OWTS guidelines. This report should be considered as a Tier 2 findings. Please keep in mind that the above findings represent only what was seen on October 13, 2023 and does not guarantee or estimate the longevity of the existing septic system. Please do not hesitate to contact us with any questions.

Signed:

Dry Solm

Greg Schram, P.E. 73540 My license expires 12/31/2024

OF CALL

COUNTY ASSESSOR'S PARCEL MAP





