

County of Sonoma
Permit & Resource Management Department
Well & Septic Section
2550 Ventura Avenue, Santa Rosa, CA 95403-2829
(707) 565-1900

SEPTIC SYSTEM INSPECTION

Site Address: 5000 Austin Creek
Owner: CAZADERO MUSIC CAMP
SEP17-0535

REQUEST FOR INSPECTION

Date of call: _____ Time: _____
Caller: _____
Caller's Phone No.: _____
Remarks: dose to be submitted.

Call taken by: _____

INSPECTION NOTICE

- Swamp #2 2 1/4" 11:26
- Stop work immediately - Call Environmental Health Specialist
Telephone _____ Hours _____
 - OK to cover leachfield tank greywater
 - Provide Engineer's letter of approval pump tank
 - Provide "As Built" plan to scale 21.5" pipe
 - Call for inspection on pump & alarm 11:27
 - Corrections needed - see remarks below Black water
 - OK to cover with Engineer's approval #1 15.5/16"
 - Issue Operational Permit 11:24
- Blackwater #2 2 1/2" 11:25a

For further information call: _____

Hours & Day: New line added.

Remarks: 3x60' trench 36" rock,
24" wide, 28" to rock. All 4
tanks passed water tightness
test. 1st. D box leak to be
fixed. Next 2 Good. Alarm
Good.

[Signature] 6/1/18
Environmental Health Specialist's Signature Date

Received by: [Signature]
Contractor's Signature

Posted