

*CHANDLER KOEHN CONSULTING*

January 13, 2022

Reference No: 2021.014

Jack and Sharon Symons  
Care of: Chandler Brothers, Inc.  
Attn.: Bob Chandler  
Sent via email to: bobhchandler@gmail.com

Subject: Foundation Plan Review for a Home Reconstruction at 4560 Brighton Drive in Santa Rosa, California.

References: 1. Foundation Plans and Details, Jack & Sharon Symons, 4560 Brighton Drive, Santa Rosa, CA, Sheets 5 and 7, by Richard A. Rocklewitz, dated February 2021.  
2. My, "Preliminary Geotechnical Investigation for a Single Family Residence at 4560 Brighton Drive in Santa Rosa, California," dated July 14, 2021.

Dear Mr. Chandler:

In accordance with your request, I have reviewed the referenced foundation plans listed above for the subject site. Based on my review, it appears that the foundation plans and details are in general conformance with my recommendations provided in the referenced Geotechnical investigation report with the following clarification.

I hope this letter provides the information that is needed at this time. If you have any questions, please feel free to contact me at (707) 972-2897.

Sincerely,



Chandler H. Koehn, P.E., G.E.  
Geotechnical Engineer



*CHANDLER KOEHN CONSULTING*

January 13, 2022

Reference No: 2021.014

Jack and Sharon Symons  
Care of: Chandler Brothers, Inc.  
Attn.: Bob Chandler  
Sent via email to: bobhchandler@gmail.com

Subject: Foundation Plan Review for a Home Reconstruction at 4560 Brighton Drive in Santa Rosa, California.


References: 1. Foundation Plans and Details, Jack & Sharon Symons, 4560 Brighton Drive, Santa Rosa, CA, Sheets 5 and 7, by Richard A. Rocklewitz, dated February 2021.  
2. My, "Preliminary Geotechnical Investigation for a Single Family Residence at 4560 Brighton Drive in Santa Rosa, California," dated July 14, 2021.

Dear Mr. Chandler:

In accordance with your request, I have reviewed the referenced foundation plans listed above for the subject site. Based on my review, it appears that the foundation plans and details are in general conformance with the recommendations provided in the referenced Geotechnical investigation report.

I hope this letter provides the information that is needed at this time. If you have any questions, please feel free to contact me at (707) 972-2897.

Sincerely,



Chandler H. Koehn, P.E., G.E.  
Geotechnical Engineer

