



MAIN OFFICE: P O BOX 1232 WINDSOR CA 95492 PHONE 707.837.0920

FINAL INSPECTION REPORT

CRT No. 24-3080

PERMIT No.

DATE 00-04-24

CLIENT

PROJECT NAME FREESTONE STORE

PROJECT ADDRESS 500 BOYEMIAN HWY. FREESTONE CA

CONTRACTOR JOHN'S EXCAVATING

SUBCONTRACTOR

IN-PLACE COMPACTED DENSITY TESTS

All Tests in accordance with ASTM D-2922 and ASTM D-1557

TEST #	LOCATION	% MOIST	% RC	DEPTH / NOTES
OBSERVED PLACEMENT AND COMPACTION OF 5FT. OF MATERIAL COMPACTED IN 8" LIFTS				
TEST RESULTS AS FOLLOWS;				
1	PLEASE SEE ATTACHED			
	TESTED 3 FT. 1 FT. GRD.	10%	97%	12" PROBE
2	TESTED 3 FT. 1 FT. GRD	11%	96%	12" PROBE
3	TESTED 3 FT. 1 FT. GRD	10.5%	96.8%	12" PROBE
4	TESTED 3 FT. 1 FT. GRD	10%	97%	12" PROBE

MATERIAL COMPACTED FILL MATERIAL 3x6 ROCK

Based on my personal inspection of the construction procedures it is my opinion that the special inspection ☐ item ☐ items inspected were performed and materials used and installed meet the requirements of the ☐ DSA ☒ CBC ☐ IBC approved documents. Non-conforming or rejected portions of the ☐ item ☐ items were reworked, repaired or replaced and reinspected for compliance. Non conforming or rejected portions which did not receive a record of correction were reported to the following parties ☐ Contractor ☐ PI ☐ Architect


SPECIAL INSPECTOR / FIELD TECHNICIAN

GM LABONTE

CRT TESTING



PLOT PLAN



DATE	SEPTEMBER 4, 2024
CLIENT	JOHN'S EXCAVATING
PROJECT NAME	FREESTONE STORE
PROJECT ADDRESS	500 BOHEMIAN HWY. FREESTONE